

DryMAX XL FIRMWARE UPDATE

Step-By-Step Guide

1 Download the DryLINK® App

The user will need to have a phone with good internet connectivity and be in close proximity to the dehumidifier to be updated.



Download DryLINK® app. To find this, search in the Apple Store or Google Play for “DryLINK®”.

Login if you have an account.

Sign-up/Login –

Create an account if you don't have one.

Once logged into the “Equipment” view, click on the “Nearby” tab. If the dehu is unclaimed, it must be claimed.



2 Claiming


If the dehu is unclaimed, a blue bar will appear at the bottom of the screen. Click on it, select your dehu and click on “ADD” to claim it.

Once the dehumidifier is claimed it should show up under “Company Units.”

IMPORTANT:


If it is not under “Company Units” it cannot be updated.

Follow the steps on the following pages to update your dehumidifier's User-Interface and Power Board Firmware.




DryMAX XL FIRMWARE UPDATE


3 Update User-Interface Board Firmware



DryMAX XL FIRMWARE UPDATE



4 Update Power Board Firmware



If this fails try the following:

Check internet connection.

Toggle the phones Bluetooth ON and OFF.

Close and Restart the App.

Power cycle the phone.

Repeat for other units from step 2 for all dehumidifiers.

DryMAX XL FIRMWARE UPDATE

For more info on DryMAX XL FIRMWARE UPDATE



USEPHOENIX.COM
1.800.533.7533